


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/96 To (mo./yr.) 12/96
2. DOGM File Number (Mine No): M / 045/028
3. Mine Name: Chemical Lime Company Grantsville Quarry
4. Mineral(s) Mined (or permitted to mine): Dolomite Limestone
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
1/4, SE 1/4, Section 25, Township 1S, Range 7W
1/4, NE 1/4, Section 36, Township 1S, Range 7W
1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Chemical Lime Company of Arizona
8. Permanent Street Address: 8777 N. Gainey Center Drive, Suite 280
City, State, Zip: Scottsdale, AZ. 85258
Phone: (800) 288-9676
9. Company Representative (or designated operator):
Name: Richard D. Beckstead
Title: Plant Chemist
Business Address: P.O. Box 537
City, State, Zip: Grantsville, Utah 84029
Phone: (801) 531-8153

☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 225,039 Tons

3. How much **additional acreage** was disturbed during the past year? None
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

All work done was within the active quarry area.

5. How much acreage was **reclaimed** during the past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

No reclamation work performed. All benches in quarry are still in use.

7. What is the **total disturbed acreage** at years end? 70 Acres

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Mining to continue in existing quarry. No reclamation is planned in the active quarry area.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Richard D. Beckstead

Title of Operator:

Plant Chemist

Signature of Operator:



Date:

March 13, 1997